


## SOCK TIMER + TEMPERATURE CONTROLLER



Model	DST 9611	DST 9411	DST 7211	DST 4911	DST 4811
Frame	96X96	96X48	72X72	48X96	48X48
Panel	92X92	92X44	68X68	44X92	44X44
Display	4 Digit 0.56" RED 4 Digit 0.39" GREEN	4 Digit 0.39" RED 4 Digit 0.39" GREEN	4 Digit 0.56" RED 4 Digit 0.39" GREEN	4 Digit 0.56" RED 4 Digit 0.28" GREEN	4 Digit 0.39" RED 4 Digit 0.28" GREEN

<b>INPUT</b>	Sensor Range	J & K OR RTD & RTD.1 2W/3W (Configurable) J(0°C to 400°C & 0°C to (600°C), K(0°C to 1200°C), PT-100 2W/3W (0°C to 400°C, - 50.0°C to 200.0°C)
<b>OUTPUT</b>	Control Output Capacity SSR	RELAY + SSR (RELAY + RELAY) 1CO, 7 Amp., 230 Volt AC 12 V DC Approximately
<b>SPECIFICATIONS</b>		
Supply Voltage	Time Range	230v AC, ±10%, 50Hz 9999 Second / Minute / Hour
Set Point	Control Mode	1 Set Point PID / Time Proportional / ON-OFF (Configurable)
Operating Mode	Accuracy	Sock + Temperature ±1% of FSD
Enclosure Material	Operating Temperature	Polycarbonate + ABS Plastic 0°C - 55°C
Relative Humidity		Upto 95% RH Non Condensing